

$$P_S = P_T \left(\eta_T \eta_A \frac{4\pi A_T}{\lambda_T^2} \right) L_{TP} L_{atm} L_{pol} L_{RP} \left(\frac{A_R}{4\pi z^2} \right) \eta_R$$